



## **Release Note**

**Edgecore EAP105 Release v12.6.6**

**Document #** EAP105-v12.6.6-2513-5d3ae89c2-b4b15ff

Enhancement from v12.6.3-2386-73ec2ed0-d9c6975

## Table of Contents

|                                                                                                                                       |          |
|---------------------------------------------------------------------------------------------------------------------------------------|----------|
| <b>1 Feature.....</b>                                                                                                                 | <b>3</b> |
| 1.1 Support Wireless and BLE Presence Data.....                                                                                       | 3        |
| <b>2 Issue Fixed .....</b>                                                                                                            | <b>5</b> |
| 2.1 The AP doesn't send a DHCP request to the DHCP relay server if DHCP relay is enabled.<br>.....                                    | 5        |
| 2.2 The CAPWAP connection is unstable when Ethernet Port #1 is selected in the VLAN ID<br>settings. ....                              | 5        |
| 2.3 Failed to obtain an IP address from the trusted DHCP server when DHCP snooping is<br>enabled.....                                 | 5        |
| 2.4 The venue type is not mapped to the correct venue group in the OpenRoaming<br>configuration. ....                                 | 5        |
| 2.5 The log size in the diagnostics log is not limited after adding the AP to the cloud.....                                          | 5        |
| 2.6 The number of associated clients is not correct on ecCLOUD when clients connect to the<br>SSID.....                               | 5        |
| 2.7 Client count by SSID on ecCLOUD doesn't decrease but keeps increasing even clients<br>have already disconnected from the AP. .... | 6        |
| <b>3 Known Issue.....</b>                                                                                                             | <b>7</b> |
| 3.1 The ARP inspection function is not operational. ....                                                                              | 7        |
| 3.2 The WDS link is not established if the wireless security is no security. ....                                                     | 7        |
| <b>4 Compatible Version for AP Management .....</b>                                                                                   | <b>8</b> |

# 1 Feature

## 1.1 Support Wireless and BLE Presence Data

The screenshot displays three configuration panels in the ecCLOUD interface:

- ADVANCED RADIO SETTINGS:**
  - Probe Req. Data Push:** Enabled (toggle switch is blue).
  - Push URL:** An empty text input field.
  - Publish MQTT:** Disabled (toggle switch is grey).
- BLE SCAN:**
  - BLE Scan:** A button labeled "BLE SCAN".
  - BLE Probe Req. Data Push:** Enabled (toggle switch is blue).
  - Publish MQTT:** Disabled (toggle switch is grey).
  - Push URL:** An empty text input field.
- MQTT:**
  - Publish MQTT:** Enabled (toggle switch is blue).
  - Topic:** local/test
  - Host:** 127.0.0.1
  - Port:** 1883
  - Client ID:** EAP\_client
  - User Name:** (empty field)
  - Password:** (empty field)
  - Interval (sec):** 5

In ecCLOUD, on the radio settings page, if Probe Req. Data Push is enabled, the 2.4GHz or 5GHz radio probe data can be pushed to a URL or an MQTT server.

On the service settings page, if BLE Probe Req. Data Push is enabled, the BLE scan data can be pushed to a URL or an MQTT server.

The MQTT interval can be set between 5 and 600 seconds.

BLE

Send iBeacon ☐ OFF

BLE Scan

BLE Probe Req. Data Push ☒ ON

MQTT

Publish MQTT ☒ ON

Interval  ?

Topic

Host

Port

Client ID

User Name

Password

In a standalone AP, on the System > Service page, if BLE Probe Req. Data Push is enabled, the BLE scan data can be pushed to an MQTT server.

The MQTT interval can be set between 5 and 600 seconds.

## 2 Issue Fixed

### 2.1 The AP doesn't send a DHCP request to the DHCP relay server if DHCP relay is enabled.

When DHCP relay is enabled on the AP, it fails to initiate or forward a DHCP request to the designated DHCP relay server, resulting in clients not receiving IP addresses as expected. In this version, the DHCP relay is working properly.

### 2.2 The CAPWAP connection is unstable when Ethernet Port #1 is selected in the VLAN ID settings.

The CAPWAP connection becomes unstable when Ethernet Port #1 is configured in the VLAN ID settings. In this version, the issue has been resolved.

### 2.3 Failed to obtain an IP address from the trusted DHCP server when DHCP snooping is enabled.

When DHCP snooping is enabled, the device is unable to obtain an IP address from the trusted DHCP server. In this version, the client can obtain an IP address from the correct DHCP server.

### 2.4 The venue type is not mapped to the correct venue group in the OpenRoaming configuration.

In the current OpenRoaming configuration, the specified venue type does not correctly correspond to its intended venue group. In this version, the issue has been resolved.

### 2.5 The log size in the diagnostics log is not limited after adding the AP to the cloud.

After the AP is added to the cloud, the log size in the diagnostics log is not limited. In this version, the issue has been resolved.

### 2.6 The number of associated clients is not correct on ecCLOUD when clients connect to the SSID.

The reported count of active wireless clients displayed within the ecCLOUD management dashboard was consistently 0. With this new version, the number of wireless clients can now be displayed correctly on ecCLOUD.

## **2.7 Client count by SSID on ecCLOUD doesn't decrease but keeps increasing even clients have already disconnected from the AP.**

Monitor client count by SSID on ecCLOUD. After operating for an extended period, the client count by SSID will keep decreasing even if clients have already disconnected from the AP. In this version, the client count by SSID on ecCLOUD displays normally.

### **3 Known Issue**

**3.1** The ARP inspection function is not operational.

**3.2** The WDS link is not established if the wireless security is no security.

## **4 Compatible Version for AP Management**

Compatible with ecCLOUD

Compatible with EWS-Series controller v3.96.0000 or later