



Release Note

Edgecore EAP105 Release v12.6.3

Document # EAP105-v12.6.3-2386-73ec2ed0-d9c6975

Enhancement from v12.6.1-2327-d27a7cb9-390f4d7

Table of Contents

1	Feature.....	3
1.1	Support WPA3 Enterprise in OpenRoaming	3
2	Issue Fixed	4
2.1	It still appears in the "Members of VLAN ID" list even when there are no VLAN settings in the SSID.	4
2.2	The TX power is not correct in the wireless status of dashboard.	4
2.3	The login page does not appear if the client is connected to the split-tunnel SSID.....	4
3	Known Issue.....	5
3.1	The ARP inspection function is not operational.	5
3.2	The client can obtain an IP address from the DHCP server even when it is not on the Trusted list of DHCP snooping.	5
3.3	The AP doesn't send a DHCP request to the DHCP relay server if DHCP relay is enabled.	5
3.4	The WDS link is not established if the wireless security is no security.	5
3.5	The CAPWAP connection is unstable when Ethernet Port #1 is selected in the VLAN ID settings.	5
4	Compatible Version for AP Management	6

1 Feature

1.1 Support WPA3 Enterprise in OpenRoaming

SECURITY SETTINGS

Method

WPA3 Enterprise

▼

OPENROAMING

OpenRoaming

ON

✓

?

OpenRoaming Profile

TestOpenRoaming

▼

OpenRoaming Settings

Configure OpenRoaming

Support WPA3 Enterprise in 2.4GHz, 5GH, and 6GHz OpenRoaming.

2 Issue Fixed

2.1 It still appears in the "Members of VLAN ID" list even when there are no VLAN settings in the SSID.

Set the SSID to Dynamic VLAN with a VLAN ID. After changing the default VLAN behavior to "Reject," the SSID is displayed in the "Members of VLAN ID" group. In this version, the issue has been resolved.

2.2 The TX power is not correct in the wireless status of dashboard.

When setting the maximum TX power on the wireless setting, the AP TX power exceeds the regulation limitation. In this version, the TX power is correct.

2.3 The login page does not appear if the client is connected to the split-tunnel SSID.

When clients connect to the split-tunnel SSID, the login page does not pop up. In this version, clients can connect to the Internet through the split-tunnel SSID.

3 Known Issue

- 3.1** The ARP inspection function is not operational.
- 3.2** The client can obtain an IP address from the DHCP server even when it is not on the Trusted list of DHCP snooping.
- 3.3** The AP doesn't send a DHCP request to the DHCP relay server if DHCP relay is enabled.
- 3.4** The WDS link is not established if the wireless security is no security.
- 3.5** The CAPWAP connection is unstable when Ethernet Port #1 is selected in the VLAN ID settings.

4 Compatible Version for AP Management

Compatible with ecCLOUD

Compatible with EWS-Series controller v3.96.0000 or later