



Release Note

Edgecore EAP102 Release v11.6.0

Document # EAP102-v11.6.0-1236-5814adf9

Enhancement from v11.5.0-1175-b0f6e6d5

Table of Contents

1	Feature.....	3
1.1	Hotspot Certificate	3
2	Issue Fixed	5
2.1	Custom LAN can't work on the mesh link	5
2.2	Client mode AP can't associate to the SSID in custom LAN	5
2.3	IOS devices are not able to get IP address when connecting to the SSID on client mode AP	5
2.4	Limit upload and download rate can't be enabled in client mode	5
2.5	AP keeps rebooting after upgrading FW	5
2.6	Internet source is incorrect in client mode	5
2.7	The members of VLAN Settings is not correct.....	5
3	Known issue.....	6
3.1	The connection of specific Microsoft surface devices is unstable using WPA2-PSK SSID	6
3.2	The SSID compatible issue in Windows 10 devices with the specific ethernet card	6
3.3	DFS channel can't be used when establishing mesh link	6
3.4	Firewall rule is not working if destination is set to "Any"	6
3.5	The throughput of mesh link decreases after reboot or reconfiguration	6
4	Compatible Version for AP Management	7

1 Feature

1.1 Hotspot Certificate

CAPTIVE PORTAL SETTINGS

HTTPS

HTTPS Domain

Customize Splash Page

Session Timeout

Idle Timeout

Landing URL

Support Https on the Hotspot Settings page of Network.

The following items are displayed on this page:

1. HTTPS — Enables HTTPS for the captive portal.
2. HTTPS Domain — The domain name of the HTTPS captive portal.

Upload Certificate

Upload Certificate	Upload Certificate of this device
Use Default Certificate	Reset to default Certificate

The following table shows properties of your current Trusted Root CA Certificate.

COUNTRY	▶ N/A
LOCALITY	▶ N/A
ORGANIZATION	▶ N/A
VERSION	▶ 3
SERIAL NUMBER	▶ AC9A7B3ED6341BFC
SIGNATURE ALGORITHM	▶ sha1WithRSAEncryption
VALID FROM	▶ Feb 26 07:01:56 2014 GMT
VALID UNTIL	▶ Nov 13 07:01:56 2033 GMT
SUBJECT KEY IDENTIFIER	▶ C0:78:AC:2D:8B:F4:00:7B:94:EF:A3:9C:6E:2E:BB:8B:03:DE:AA
IS CERTIFICATE AUTHORITY	▶ TRUE

Support upload certificate for hotspot HTTPs certificate on the Upload certificate page of

System.

The following items are displayed on this page:

1. Upload Certificate — Click to upload a security certificate and private key from a trusted certification authority.
2. Use Default Certificate — Click to reset to use the AP's default certificate.

2 Issue Fixed

2.1 Custom LAN can't work on the mesh link

Set the mesh network behavior of AP1 to route to internet with custom LAN and establish the mesh link with AP2. AP2 can't get the correct IP address from AP1. This issue has been resolved in this version.

2.2 Client mode AP can't associate to the SSID in custom LAN

AP1 SSID sets to route to internet with custom LAN. Client mode AP can't associated to the SSID of AP1. This issue has been resolved in this version.

2.3 IOS devices are not able to get IP address when connecting to the SSID on client mode AP

Client mode AP is associated to the SSID of AP. IOS devices can't get the IP address from the 2.4Ghz SSID with bridge to internet in client mode AP. This issue has been resolved in this version.

2.4 Limit upload and download rate can't be enabled in client mode

Modify the mode from Access point to Client mode in the wireless radio page. Limit upload and download rate can't be enabled successfully. This issue has been resolved in this version.

2.5 AP keeps rebooting after upgrading FW

The country of AP is set to Netherland. If upgrading FW from 11.3.1 or previous version to 11.4.0 or 11.5.0, AP will keep rebooting. This issue has been resolved in this version.

2.6 Internet source is incorrect in client mode

Modify the mode from Client mode to Access point in the wireless radio page. The Internet source is not correct in Dashboard. This issue has been resolved in this version.

2.7 The members of VLAN Settings is not correct

Create the VLAN Id in VLAN Settings page. Configure network behavior of 5 GHz to VLAN tag traffic. This 5 GHz SSID can't be displayed in the members of VLAN Settings page. This issue has been resolved in this version.

3 Known issue

3.1 The connection of specific Microsoft surface devices is unstable using WPA2-PSK SSID

If the 5Ghz SSID is set to WPA2-PSK SSID, the connection of some Microsoft surface devices is unstable.

3.2 The SSID compatible issue in Windows 10 devices with the specific ethernet card

Using Intel AX200 (old version) or Realtek RTL8822BE with Windows 10 devices, the connection of the devices is unstable connecting to the SSID.

Note that there is no connection issue if the driver of Intel AX200 is updated to 22.60.0.6 or later version.

3.3 DFS channel can't be used when establishing mesh link

If DFS channel is used, mesh link can't be established successfully.

3.4 Firewall rule is not working if destination is set to "Any"

3.5 The throughput of mesh link decreases after reboot or reconfiguration

In mesh topology, after AP reboots or reconfigure the wireless configuration, the throughput of mesh link will decrease.

4 Compatible Version for AP Management

Compatible with ecCLOUD

Compatible with EWS5203 v3.50.0000 or later