Release Notes
MLTG-CN LR

Version: 1.3.1-00545-254358c
Enhanced from version 1.3.0-00536-dd35b43

Copyright Notification

Edgecore Networks Corporation

Table of Content

1. Issue Fixed

- Fix an issue that the VXLAN tunnel disconnection occurs during throughput test. This fix ensures the resource assignment is optimized and make sure the control frames will not be dropped during high rate data transmission.

2. Known Issue

- Sometimes existing link is not shown on the link status page.
- In Point-to-point mode, after deleting Peer MAC address, the link will not be associated until manually rebooting the unit.