Edge-corE

Release Note

Edgecore OAP100 Release v3.45.0002
Document # OAP100-v3.45.0002_1.4.4.3-1.9759.6.2

Enhancement from v3.45.0001_1.4.4.1-1.9759.6.1

Table of Contents

1 Issue Fixed

1.1 The bitflips occur in the flash memory under certain conditions.

Resolved an issue where bitflips were occurring in the flash memory under certain conditions. This fix ensures data integrity and prevents unexpected behavior caused by corrupt data.

2 Compatible Version for AP Management

Compatible with EWS-Series controller v3.45.0000 or later