



Release Note

Edgecore EWS100 Release v3.45.0401

Document # Edgecore_EWS100_v3.45.0401_1.22-1.9733.2.15

Enhancement from v3.45.0300_1.19-1.9733.2.13

Table of Contents

1	AP Management Compatibility	3
1.1	Compatible Versions for AP Management	3
2	Issue Fixed	4
2.1	LAPM can manage AP ECW5210-L, ECW5410-L.....	4
2.2	Users click only one time on the link of mail verification.....	4
2.3	802.11X authentication can work successfully.....	4
2.4	The quota column shows correctly in Social Media Login Page.....	4
2.5	InnKeyPMS can be applied successfully in PMS Interface Page	4
2.6	Correct the string of VAP Configuration Page in LAPM Template Page.....	4
2.7	Fix the IP Discovery function in Network Utilities Page	4
2.8	Fix the display issue of WAN status in Interfaces Page	4

1 AP Management Compatibility

1.1 Compatible Versions for AP Management

AP type	LAPM	WAPM	Compatible version
OAP100	V	V	3.45.0000 or newer
EAP100	V	V	3.45.0000 or newer
ECW100	V	V	3.45.0000 or newer
ECW5210-L	V	V	3.45.0000 or newer
ECW5211-L	V	V	3.45.0000 or newer
ECW5410-L	V	V	3.45.0000 or newer
ECWO5210-L	V	V	3.45.0000 or newer
ECWO5211-L	V	V	3.45.0000 or newer
ECWO5212-L	V	V	3.43.20 or newer
ECWO5213-L	V	V	3.45.0000 or newer
3rd Party		V	

- *OAP100 and EAP100 are supported to be managed in LAPM and WAPM now.*

2 Issue Fixed

- 2.1 LAPM can manage AP ECW5210-L, ECW5410-L**
- 2.2 Users click only one time on the link of mail verification**
- 2.3 802.11X authentication can work successfully**
- 2.4 The quota column shows correctly in Social Media Login Page**
- 2.5 InnKeyPMS can be applied successfully in PMS Interface Page**
- 2.6 Correct the string of VAP Configuration Page in LAPM Template Page**
- 2.7 Fix the IP Discovery function in Network Utilities Page**
- 2.8 Fix the display issue of WAN status in Interfaces Page**