



## Release Note

**Edgecore EWS5204 Release v3.97.0002**

**Document #** Edgecore\_EWS5204\_ERN\_v3.97.0002

Enhancement from v3.96.0002

---

### Copyright Notification

### Edgecore Networks Corporation

© Copyright 2023 Edgecore Networks Corporation.

The information contained herein is subject to change without notice. This document is for informational purposes only and does not set forth any warranty, expressed or implied, concerning any equipment, equipment feature, or service offered by Edgecore Networks Corporation. Edgecore Networks Corporation shall not be liable for technical or editorial errors or omissions contained herein.

## Revision History

Date	Version	Author	Remark
2025/ 3 / 17	V1.0	Vincent Cheng	Release Note for v3.97.0002

## Table of Contents

1	AP Management Compatibility.....	3
1.1	Compatible Versions for AP Management.....	3
2	Feature Enhancement.....	4
2.1	Support EAP105 management.....	4
2.2	Support EAP111 management.....	4
3	Issue Fixed.....	5
3.1	Popup the web notification to alert users when mac authentication got failed.....	5
3.2	Fix Bad Gateway message was observed on the EAP102 GUI while management from ecCLOUD change to EWS5203 .....	5
3.3	Support OID: 1.3.6.1.4.1.259.3.1.19 for controller's WAN MAC address.....	5
3.4	Fix template default 6G SSID password will missed after F/W upgrade issue, it will caused AP CAPWAP connection keep restarting. ....	5

# 1 AP Management Compatibility

## 1.1 Compatible Versions for AP Management

AP type	LAPM	WAPM	Compatible version
OAP100	V	V	3.45.0000 or newer
OAP100e	V	V	3.45.0000 or newer
EAP100	V	V	3.45.0000 or newer
ECW100	V	V	3.45.0000 or newer
ECW5210-L	V	V	3.45.0000 or newer
ECW5211-L	V	V	3.45.0000 or newer
ECW5410-L	V	V	3.45.0000 or newer
ECWO5210-L	V	V	3.45.0000 or newer
ECWO5211-L	V	V	3.45.0000 or newer
ECWO5213-L	V	V	3.45.0000 or newer
OAP101		V	12.4.1 or newer
OAP101e		V	12.4.1 or newer
OAP101-6E		V	12.4.1 or newer
OAP101e-6E		V	12.4.1 or newer
OAP103-BR		V	11.6.4 or newer
EAP101		V	11.2.0-795 or newer
EAP102		V	11.2.0-796 or newer
EAP102-Lite		V	11.2.0-796 or newer
EAP104		V	12.0.0 or newer
EAP105		V	12.6.0 or newer
EAP111		V	12.6.0 or newer
SP-W2M-AC1200		V	7.0.0-2987 or newer
3rd Party		V	

## **2 Feature Enhancement**

**2.1 Support EAP105 management**

**2.2 Support EAP111 management**

### **3 Issue Fixed**

**3.1 Popup the web notification to alert users when mac authentication got failed.**

**3.2 Fix Bad Gateway message was observed on the EAP102 GUI while management from ecCLOUD change to EWS5203**

**3.3 Support OID: 1.3.6.1.4.1.259.3.1.19 for controller's WAN MAC address**

**3.4 Fix template default 6G SSID password will missed after F/W upgrade issue, it will caused AP CAPWAP connection keep restarting.**