



Release Note

Edgecore SDW10x Release v1.5.0.5

Document # Edgecore_SDW10x_ERN_v1.5.0.5

Enhancement from v1.5.0.4

Copyright Notification

Edgecore Networks Corporation

© Copyright 2023 Edgecore Networks Corporation.

The information contained herein is subject to change without notice. This document is for informational purposes only and does not set forth any warranty, expressed or implied, concerning any equipment, equipment feature, or service offered by Edgecore Networks Corporation. Edgecore Networks Corporation shall not be liable for technical or editorial errors or omissions contained herein.

Revision History

Date	Version	Author	Remark
2023/ 3 / 13	V1.0	Vincent Cheng	Release Note for v1.5.0.5

Table of Contents

1	Feature Enhancement.....	3
1.1	Tunnel status	3
2	Issue Fixed.....	4
2.1	Fix the routing table can't display all data on the live utility page when there are many routing rules.....	4
2.2	Fix VLAN Tagged port can't shows Link speed and Link duplex status when the port is linked on Site Information web page	4
2.3	Fix default LAN port status always shows link down even if the port is linked on the Site Information web pag	4
2.4	To remove the unused virtual interface.....	4

1 Feature Enhancement

1.1 Tunnel status

Add Tunnel status in dashboard

2 Issue Fixed

2.1 Fix the routing table can't display all data on the live utility page when there are many routing rules

2.2 Fix VLAN Tagged port can't shows Link speed and Link duplex status when the port is linked on Site Information web page

2.3 Fix default LAN port status always shows link down even if the port is linked on the Site Information web pag

2.4 To remove the unused virtual interface