

## Release Notes MLTG-CN

Version: 1.1.2-00414-1a69c39

## **Table of Content**

1.	Issue Fixed	2
2.	Known Issue	2

## 1. Issue Fixed

• In Bridge Mode, web pages can proceed and refresh automatically after the configuration changes are applied successfully.

## 2. Known Issue

• In NAT6 mode (Terragraph mode), if the LAN Settings are modified after the 60GHz link is established, it requires an additional reboot to make the VXLAN tunnel work normally.