



Release Note

Edgecore EWS5203 Release v3.60.0102

Document # Edgecore_EWS5203_ERN_v3.60.0102

Enhancement from v3.60.0100

Copyright Notification

Edgecore Networks Corporation

© Copyright 2021 Edgecore Networks Corporation.

The information contained herein is subject to change without notice. This document is for informational purposes only and does not set forth any warranty, expressed or implied, concerning any equipment, equipment feature, or service offered by Edgecore Networks Corporation. Edgecore Networks Corporation shall not be liable for technical or editorial errors or omissions contained herein.

Revision History

Date	Version	Author	Remark
2022/ 11 / 16	V1.0	Bill Chen	Release Note for v3.60.0102

Table of Contents

1	AP Management Compatibility.....	3
1.1	Compatible Versions for AP Management.....	3
2	Issue Fixed.....	4
2.1	In WAPM, the ECW5211-L information and online users are not correct in the AP list.	4
2.2	In WAPM, there is an error message “reboot-Access denied” occasionally when applying the New Generation template to the AP.....	4
2.3	In WAPM, the WPA3 Enterprise 192-bit configuration of AP is not correct after applying the New Generation template to the AP.....	4
3	Known Issue	5
3.1	In WAPM, the Access Control List in New Generation template can’t have more than 64 MACs. 5	

1 AP Management Compatibility

1.1 Compatible Versions for AP Management

AP type	LAPM	WAPM	Compatible version
OAP100	V	V	3.45.0000 or newer
OAP100e	V	V	3.45.0000 or newer
EAP100	V	V	3.45.0000 or newer
ECW100	V	V	3.45.0000 or newer
ECW5210-L	V	V	3.45.0000 or newer
ECW5211-L	V	V	3.45.0000 or newer
ECW5410-L	V	V	3.45.0000 or newer
ECWO5210-L	V	V	3.45.0000 or newer
ECWO5211-L	V	V	3.45.0000 or newer
ECWO5213-L	V	V	3.45.0000 or newer
OAP103-BR		V	11.6.4 or newer
EAP101		V	11.2.0-795 or newer
EAP102		V	11.2.0-796 or newer
EAP104		V	12.0.0 or newer
SP-W2M-AC1200		V	7.0.0-2987 or newer
3rd Party		V	

2 Issue Fixed

2.1 In WAPM, the ECW5211-L information and online users are not correct in the AP list.

2.2 In WAPM, there is an error message “reboot-Access denied” occasionally when applying the New Generation template to the AP.

2.3 In WAPM, the WPA3 Enterprise 192-bit configuration of AP is not correct after applying the New Generation template to the AP.

3 Known Issue

3.1 In WAPM, the Access Control List in New Generation template can't have more than 64 MACs.