



Release Note

Edgecore EWS101 Release v3.93.0003

Document # Edgecore_EWS101_ERN_v3.93.0003

Enhancement from v3.92.0005

Copyright Notification

Edgecore Networks Corporation

© Copyright 2023 Edgecore Networks Corporation.

The information contained herein is subject to change without notice. This document is for informational purposes only and does not set forth any warranty, expressed or implied, concerning any equipment, equipment feature, or service offered by Edgecore Networks Corporation. Edgecore Networks Corporation shall not be liable for technical or editorial errors or omissions contained herein.

Revision History

Date	Version	Author	Remark
2024/ 4 / 1	V1.0	Vincent Cheng	Release Note for v3.93.0002

Table of Contents

1	AP Management Compatibility.....	3
1.1	Compatible Versions for AP Management.....	3
2	Feature Enhancement.....	4
2.1	Support IPv6 by DHCP.....	4
2.2	Use AP hostname for AP name on Discovery AP function	4
2.3	Support change AP hostname by import from cvs file.	4
3	Issue Fixed.....	5
3.1	PHP dump files were produced on HA mode	5
3.2	Radio information in "# of of Users" is not correct	5
4	Known Issue	6
4.1	Because image size is more then web limitation, need to upgrade to 3.93.0002 firstly then upgrade to this version.	6

1 AP Management Compatibility


1.1 Compatible Versions for AP Management

AP type	LAPM	WAPM	Compatible version
OAP100	V	V	3.45.0000 or newer
OAP100e	V	V	3.45.0000 or newer
EAP100	V	V	3.45.0000 or newer
ECW100	V	V	3.45.0000 or newer
ECW5210-L	V	V	3.45.0000 or newer
ECW5211-L	V	V	3.45.0000 or newer
ECW5410-L	V	V	3.45.0000 or newer
ECWO5210-L	V	V	3.45.0000 or newer
ECWO5211-L	V	V	3.45.0000 or newer
ECWO5213-L	V	V	3.45.0000 or newer
OAP101		V	12.4.1 or newer
OAP101e		V	12.4.1 or newer
OAP101-6E		V	12.4.1 or newer
OAP101e-6E		V	12.4.1 or newer
OAP103-BR		V	11.6.4 or newer
EAP101		V	11.2.0-795 or newer
EAP102		V	11.2.0-796 or newer
EAP102-Lite		V	11.2.0-796 or newer
EAP104		V	12.0.0 or newer
SP-W2M-AC1200		V	7.0.0-2987 or newer
3rd Party		V	

2 Feature Enhancement

2.1 Support IPv6 by DHCP

To support IPv6 by DHCP on SYSTEM > IPv6 page



IPv6 Setting	
IPv6	<input checked="" type="radio"/> Enable <input type="radio"/> Disable
Interface	<input checked="" type="radio"/> WAN1 <input type="radio"/> WAN2
Type	<input type="radio"/> Static (Use the following IPv6 settings) <input type="radio"/> Use 6to4 transition <input checked="" type="radio"/> DHCP

2.2 Use AP hostname for AP name on Discovery AP function

To get AP name from current AP hostname on Discovery AP page

2.3 Support change AP hostname by import from cvs file.

Support sync AP name to AP hostname by import cvs file on Import AP List > Update

3 Issue Fixed

3.1 PHP dump files were produced on HA mode

3.2 Radio information in "# of of Users" is not correct

4 Known Issue

4.1 Because image size is more then web limitation, need to upgrade to 3.93.0002 firstly then upgrade to this version.