



Release Note

Edgecore EWS101 Release v3.94.0004

Document # Edgecore_EWS101_ERN_v3.94.0004

Enhancement from v3.93.0005

Copyright Notification

Edgecore Networks Corporation

© Copyright 2023 Edgecore Networks Corporation.

The information contained herein is subject to change without notice. This document is for informational purposes only and does not set forth any warranty, expressed or implied, concerning any equipment, equipment feature, or service offered by Edgecore Networks Corporation. Edgecore Networks Corporation shall not be liable for technical or editorial errors or omissions contained herein.

Revision History

Date	Version	Author	Remark
2024/ 6 / 3	V1.0	Vincent Cheng	Release Note for v3.94.0004

Table of Contents

1	AP Management Compatibility.....	3
1.1	Compatible Versions for AP Management.....	3
2	Feature Enhancement.....	4
2.1	Automatically delete expired on-demand account	4
3	Issue Fixed.....	5
3.1	Fix nas_port_id get incorrect value will caused Client always need to do authentication in connection process.	5
3.2	Improve the method to update AP firmware version in AP List to fix the AP version display not match with AP issue.	5
3.3	Fix incorrect TX power in template will caused EAP101 power change to 3dBm issue.	5

1 AP Management Compatibility

1.1 Compatible Versions for AP Management

AP type	LAPM	WAPM	Compatible version
OAP100	V	V	3.45.0000 or newer
OAP100e	V	V	3.45.0000 or newer
EAP100	V	V	3.45.0000 or newer
ECW100	V	V	3.45.0000 or newer
ECW5210-L	V	V	3.45.0000 or newer
ECW5211-L	V	V	3.45.0000 or newer
ECW5410-L	V	V	3.45.0000 or newer
ECWO5210-L	V	V	3.45.0000 or newer
ECWO5211-L	V	V	3.45.0000 or newer
ECWO5213-L	V	V	3.45.0000 or newer
OAP101		V	12.4.1 or newer
OAP101e		V	12.4.1 or newer
OAP101-6E		V	12.4.1 or newer
OAP101e-6E		V	12.4.1 or newer
OAP103-BR		V	11.6.4 or newer
EAP101		V	11.2.0-795 or newer
EAP102		V	11.2.0-796 or newer
EAP102-Lite		V	11.2.0-796 or newer
EAP104		V	12.0.0 or newer
SP-W2M-AC1200		V	7.0.0-2987 or newer
3rd Party		V	

2 Feature Enhancement

2.1 Automatically delete expired on-demand account

Automatically delete the on-demand account after it expires.

3 Issue Fixed

3.1 Fix nas_port_id get incorrect value will caused Client always need to do authentication in connection process.

3.2 Improve the method to update AP firmware version in AP List to fix the AP version display not match with AP issue.

3.3 Fix incorrect TX power in template will caused EAP101 power change to 3dBm issue.